

Juniper Networks

NetScreen Engineering notes for ScreenOS special release
5.4.0r3a

Product(s): NS-HSC, NS-5GT, NS-5GT-ADSL, NS-5GT-Wireless, NS-5GT-Wireless&ADSL, SSG-5 (&Wireless,ADSL, ISDN, V92), SSG-20 (& Wireless), SSG-140, NS-25, NS-50, NS-204, NS-208, SSG-520, SSG-550, SSG-520M, SSG-550M, NS-500, ISG-1000, ISG-1000-IDP, ISG-2000, ISG-2000-IDP, NS-5000-MGT1, NS-5000-MGT2, All NS-5000 Linecards (8G, 24FE, 8G2, 2XGE)

Version: Engineering release 5.4.0r3a

Document version: V1
Date: 2-12-07

Note: This Engineering Note is an addendum to the ScreenOS 5.4.0r3 Release Notes. Additionally, this version of ScreenOS is based in ScreenOS 5.4.0r3 and may only be available until the next public mainline release which will contain these fixes. The notes below do not contain all included fixes, known issues and other information available in the mainline release notes. Therefore it should be used as an addendum to the current 5.4.0r3 release notes and previous engineering notes.

1. Addressed issue(s) in Special Engineering release 5.4.0r3a

| Bug ID | Description |
|---------------|---|
| cs12914 | Login to the WebUI for administration via HTTPS would fail unless you first logged in via HTTP. |